


Northumberland County Before and After Pictures for 310 ECE Inspection

Graffiti

Before:



After:



Vent requiring cleaning (inside)

Before:



After:



Vents requiring cleaning (outside)

Before:



After:



Peeling Paint

Before:



After:



Outside Mesh Loose

Before:



After:



Outside Electrical Box Loose

Before:



After:



Accessibility Parking Spot:

After:



Flagpole:

After:

